
## ProPride Hitch Pre-Trip Checklist

- Visual Inspection
  - o Clear off any dirt and debris
  - Keep it clean, wipe it off, even apply your favorite show and shine (wax) if you'd like!
- Check for component proper placement (Has anything shifted)
  - Weight Distribution Jacks
  - Center Frame Bracket
- Check for loose bolts (Torque Spec Sheet)



- Lube your components
  - Take a moment to make sure your hitch has all the movement it deserves.
    - Spring Bar Grease Zerks
    - Legacy Jacks Oil hole
    - Multi-purpose silicone spray all moveable joints
      - OCLS
      - V2 Jacks
      - Yoke arms
      - Even on the hitch bar and hitch bar opening

## 3P General Maintenance

- Keep it clean and free of debris. Treat your hitch like you treat your car and trailer!
- Add Marine Grade Grease
  - Spring Bars
    - Apply through zerk fittings, every 1000 miles or as needed. If you hear any
      noises coming from this area, check to make sure they are adequately
      greased. Grease should be slowly pumped in until you see it starting to
      appear where spring bar is inserted.
  - Ball
    - Apply enough to cover the ball. This should be done every 12-18 months or as needed.
- Lube/ condition (silicone spray) moving parts on main and jacks
  - OCL (Over Center Latches) and OCL Screws
    - Apply spray, move OCL back and forth assuring smooth movement. Apply spray to the OCL screw (keep in mind position) screw in a couple turns each way to make sure they have smooth non-binding movement.
  - Backside of Weight Distribution Jack (OIL hole)
    - Insert tip of straw into OIL hole on backside of Weight Distribution Jack and spray in a couple pumps. Just enough to keep the welded outer sleeve beads moving smoothly along the inner sleeve groove.
- Bearing Inspection every 4 years or 50,000 miles. Repack or replacement may be needed. (Complete bearing kit available at online store)
- Chips or scratches to powder coat finish
  - Clean effected spot thoroughly with soap and water to remove any existing corrosion, dirt or debris. (prep surface) If needed, lightly sand to remove. Apply Phantom Black or similar paint to effected area.



All in one Hitch Maintenance Kit Available at www.ProPrideHitch.com